




ONGAR - Phase 1 Diagram of Signals



N
↑



"h" INDICATES HAND POINTS

17 - King Lever

Notes: Spares 1-8, 16, 18, 29, 30

v09, Dwn: SH, Checked: CM, (April 13)