




ONGAR - Phase 1

Diagram of Signals



- 11 DOWN HOME - ROUTE SELECTED BY:
 12 ROUTE TO LOOP - "1"
 13 ROUTE TO DOWN MAIN PLATFORM - "3"
 14 ROUTE TO PLAT 2 - "2"
 15 ROUTE TO PLAT 1 - "1"

26 - KING LEVER "h" INDICATES HAND POINTS

- 30 - SHUNTERS RELEASE:
 ① - RELEASE + FPL ON 2
 ② - POINTS

Notes: Spares 1-8.

v07j, Dwn: SH, Checked: CM, (May 10)